

General Environmental Incident Summary

Incident: 3364 **Date/Time Notice:** 6/24/2014 1645 **DEM Incident No:**

Responsible Party: BOE Pipeline

Date Incident: 6/21/2014 **Time Incident:** 1200 **Duration:** 20 minutes

County: Dunn **Twp:** 143 **Rng:** 96 **Sec:** 1 **Qtr:** NW NW NW

Lat: 47.24120 **Long:** -102.79950 **Method:** Interpolation from map

Location Description: On the access road into the field in Section 1, south of 12th Street and on 109th Avenue (the access road into the field)

Submitted By: Glenn Carpenter

Affiliation: KLJ

Address: 4585 Colemam Street

City: Bismarck

State: ND

Zip: 58503

Received By:

Contact Person: John Wadsworth
8301 East 21st North
Suite 420
Wichita, KS 67206

Distance Nearest Occupied Building: 1.2 Miles

Release Contained: Yes

Type of Incident: Diesel Spill

Description of Released Contaminant: Diesel

Volume Spilled: 12.00 cubic yards

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

The area is adjacent to the BOE pipeline worksite. There were trucks and heavy equipment in the area. Precise cause is unknown.

Risk Evaluation:

Minimal

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

There will be no long term impacts.

Action Taken or Planned:

The contaminated soil was removed and secured in a location near the headquarters office at the ending point of the project.

Wastes Disposal Location: To be determined

Agencies Involved:

Updates

Date: 6/24/2014

Status: Reviewed; Followup Required

Staff: Roberts, Kris

Updated Volume:

Notes:

Diesel spill from an unknown source. Cleaned up and stockpiled for disposal according to the report. Followup is necessary.

Date: 7/16/2014

Status: Inspected

Staff: Stockdill, Scott

Updated Volume:

Notes:

Arrived on location at 12:05 7/16/2014.

No sign of a spill at the stated location. Large amount of land has been recently worked due to a pipeline being put in at the location.

Follow-up call with company to get the exact details of cleanup.